

## Photos of Erie Community Center Water Slide and Tower Existing Areas of Concern

Spider cracks in slide:



Rusting Bolts:



Shifting Seams:

