


# Erie Parkway Bridge Revegetation Project

Town Board of Trustees Meeting


January 12, 2021

# Revegetation Site Maps



Erie Parkway Bridge - Native Meadow Area



Erie Parkway Bridge - Riparian Area



# Revegetation Site Maps



# Existing Vegetation Conditions 2020



Figure 1. Soil surface conditions observed on the south side of Erie Parkway. This material will need to be removed to ensure successful germination.



Figure 2. Detail of the surface soil conditions that will impair reclamation success on either side of Erie Parkway.



Figure 3. Detention pond at corner of Erie Parkway and Montgomery Drive



Figure 4. Straw wattles with sediment build up on the upslope position at each placement.